Service Bulletin

Inspect Forward Facing Camera Pitch Angle

SB-23-17-006 July 19, 2023

July 19,	2023				
Classification			Section/Group	Mobile Service	Configuration
Recall Bulletin		17 - Electrical	Can Perform (where permitted)	HW4	
Model Year	Model		Country/Region	Build Location	
2023	Model S, Mo	del X,	All	All	
	Model Y				

The model(s) and model year(s) listed are a general approximation of the affected VIN list. Refer to the VIN/Bulletin Tracker or Customer/Vehicle profile to determine applicability of this bulletin for a particular vehicle.

Recall Bulletin: Recall Bulletins are mandatory service procedures that, unless they can be completed via a software update that a customer installs through the normal course of ownership, must be carried out by Tesla-certified Service Centers. Recall work performed by uncertified technicians could lead to unsafe conditions or voided warranty provisions.

Condition

Some Model S, Model X, and Model Y vehicles may require adjustment to the forward facing camera pitch angle.

Correction

Inspect the vehicle for symptoms related to the condition. If symptoms are present, adjust the forward facing camera pitch angle to specification.

Correction Description	Correction	Model S	Time Model X	Model Y
Inspect The Forward Facing Camera Pitch Angle; No Adjustment Needed	S012317006	0.18	0.24	0.18
Inspect The Forward Facing Camera Pitch Angle; Adjust To Required Specification	S022317006	0.18	0.24	0.18

Special Tools 1053066-00-A CAMERA CALIBRATION TARGET 1448868-00-B PITCH ADJUSTMENT WRENCH

These part numbers were current at the time of publication. Use the revisions listed or later, unless otherwise specified in the Parts Catalog.

Procedure

Perform the forward facing camera pitch verification procedure (refer to Service Manual procedure 17221000 for Model S, Model X, or 17230600 for Model Y).