OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-561

Manufacturer Name: Explorer Van Company

Submission Date: AUG 08, 2023 NHTSA Recall No.: 23V-561 Manufacturer Recall No.: PG5215



Manufacturer Information:

Manufacturer Name: Explorer Van Company

Address: 2749 Fox Farm Rd

Warsaw IN 46580

Company phone: 267-7666

Population:

Number of potentially involved : 8 Estimated percentage with defect : 75%

Vehicle Information:

Vehicle 1: 2020-2022 GMC SAVANA

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: VAN
Power Train: GAS
Descriptive Information: A

Production Dates: FEB 05, 2020 - AUG 23, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: The fuel hose between the inline fuel filter and pump may have inadequate

clamp force, possibly resulting in a gas leak

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A gas leak in the presence of an ignition source may increase the risk of fire.

Description of the Cause: Cause of issue is an inadequate specification of the fuel hose.

Identification of Any Warning Bystanders may see or smell gas

that can Occur:

Involved Components:

Part 573 Safety Recall Report

23V-561

Page 2

Component Name 1: Onan OG 2800i

Component Description: Generator

Component Part Number: 2.8hglaa-8302a

Supplier Identification:

Component Manufacturer

Name: Cummins Inc

Address: Po Box 3005 Mail Code COB118

Columbus Ohio 47202-3005

Country: United States

Chronology:

NR

Description of Remedy:

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: 0

Planned Dealer Notification Date : AUG 08, 2023 - SEP 08, 2023 Planned Owner Notification Date : AUG 08, 2023 - SEP 08, 2023

^{*} NR - Not Reported