

Safety Recall Interim Notification 23KWG: K270/K370 Dana Driveline Welds

Number

[Edit](#) [Clone](#)

23KWG/ 23V616 / 2023-496

Supplier

Dana

Description

Safety Recall: K270/K370 Dana Driveline Welds

Date

9/22/2023

What's New

Safety Recall: Interim Notification

On certain Kenworth K270/K370 chassis equipped with Dana SPL100 drivelines, the driveline tube seam weld may separate or tear under certain stress loads, resulting in driveline separation and sudden loss of drive power. A sudden loss of drive power may increase the risk of a crash.

Situation

3 (3 U.S. and 0 Canada) Model Year 2023 Kenworth K270/K370 chassis built from 8/29/22 through 10/05/22 equipped with Dana SPL100 drivelines

with suspect driveline serial numbers.

Resolution

Safety Recall: Interim Notification

This bulletin will be updated when repair parts and procedure are available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[Chassis List](#)

Authored by: BDS