



New Safety Recall Advanced Communication – 92A

FCA US LLC (FCA US) has announced a safety recall on certain 2022 and 2023 model year (JL) Jeep® Wrangler and (JT) Jeep® Gladiator vehicles equipped with a manual transmission.

VINs identified as being involved in this campaign are currently live and searchable.
Stop sale is in effect for the above-identified vehicles.

Vehicles impacted by a stop sale are eligible for reimbursement allowance through the Recall Floorplan Reimbursement Policy (RFPRP), which can be requested upon recall claim submission.

IMPORTANT: Some of the involved vehicles may be in dealer new vehicle inventory. Federal law requires you to complete this recall service on these vehicles before retail delivery. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Involved vehicles can be determined by using the VIP inquiry process.

REASON FOR THIS SAFETY RECALL

Some manual transmissions have been built with an improperly manufactured Gear Position Sensor / All Gear Sensor (AGS) which may cause the reverse lights and back-up camera to be disabled. Vehicles with a suspect Gear Position Sensor / AGS may not display the rearview image or activate the backup lamps during a backing event. The vehicle operator will notice that the rearview image is not displayed if attempting to reference the image while backing. If this warning is not heeded, backing without verifying it is safe to do so could lead to an increased risk of injury to people outside the vehicle. Failure to illuminate the backup lamps may not adequately illuminate the roadway behind the vehicle or indicate to other drivers or pedestrians the intention to backup, which can cause a crash without prior warning.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.111 S6.2.6 requires that "The rear visibility system default to the rearview image being visible and meet the requirements of FMVSS No. 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected...". FMVSS No. 571.108 requires that backup lamps "Must be activated when the ignition switch is energized and reverse gear is engaged."

SERVICE ACTION

FCA US will conduct a voluntary safety recall to replace the Gear Position Sensor / AGS. The remedy for this condition is not currently available. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 4th Quarter of 2023.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC