

U.S. Department of Transportation

National Highway Traffic Safety Administration

October 24, 2023

1200 New Jersey Avenue SE Washington, DC 20590

Mr. Craig Ries Terex South Dakota, Inc. 3140 15th Ave SE Watertown, SD 57201 NEF-107DC 23V-703

Subject: Aerial Device Mounting Bolts Improperly Tightened

Dear Mr. Ries:

This letter serves to acknowledge Terex South Dakota, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

### Makes/Models/Model Years:

TEREX/TL48/2021-2023

Mfr's Report Date: October 19, 2023

NHTSA Campaign Number: 23V-703

### **Components:**

EQUIPMENT:MECHANICAL:BOOM/CRANE/LADDER:TURNTABLE

Potential Number of Units Affected: 17

# **Problem Description:**

Terex South Dakota, Inc. (Terex) is recalling certain 2021-2023 TL48 trucks. The bolts used to mount the aerial device to the subbase may not be tightened properly, which could result in bolt failure, allowing the aerial device to fall.

## **Consequence:**

An aerial device that falls increases the risk of injury.

### Remedy:

Dealers will replace the mounting bolts and washers, free of charge. Owner notification letters are expected to be mailed November 17, 2023. Owners may contact Terex customer service at 1-605-882-4000. Terex's number for this recall is SN723.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received Terex South Dakota, Inc.'s proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Terex South Dakota, Inc.'s contact for this recall will be Debora Crews who may be reached by email at debora.crews@dot.gov. We look forward to working with you.

Sincerely.

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Alex Andy

Enforcement

