

Part 573 Safety Recall Report

23V-728

Manufacturer Name : Winnebago Industries, Inc.**Submission Date :** OCT 27, 2023**NHTSA Recall No. :** 23V-728**Manufacturer Recall No. :** 180**Manufacturer Information :****Manufacturer Name :** Winnebago Industries, Inc.**Address :** PO BOX 152
605 W. Crystal Lake Rd. Forest City IA
50436**Company phone :** 1-641-585-3535**Population :****Number of potentially involved :** 280**Estimated percentage with defect :** 100 %**Vehicle Information :****Vehicle 1 :** 2024-2024 Winnebago Solis**Vehicle Type :****Body Style :****Power Train :** NR**Descriptive Information :** The basis for determining the recall population is to include all T36B units built from start of production.**Production Dates :** JUN 30, 2023 - OCT 23, 2023**VIN Range 1 : Begin :**

NR

End : NR☐ Not sequential**Description of Noncompliance :****Description of the Noncompliance :** Required fasteners for seating compliance to FMVSS 207 are missing.**FMVSS 1 :** 207 - Seating systems**FMVSS 2 :** NR**Description of the Safety Risk :** Failure to meet FMVSS 207 can increase the risk of injury in the event of a crash.**Description of the Cause :** During installation of the structure used to secure the sliding seat, two fasteners were not installed.**Identification of Any Warning that can Occur :** There are no warnings which occur.**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On or about October 18, 2023 during normal quality inspections, two fasteners were identified missing from the structure used to secure the sliding seat in the extended position. An investigation was opened. The Product Safety Committee met to review the findings of the investigation, at which time it was determined the missing fasteners presented an unreasonable risk to motor vehicle safety and were non-compliant to FMVSS 207.

Winnebago is not aware of any incidents or injuries related to the recall condition.

Description of Remedy :

Description of Remedy Program : Remedy to correct the recall condition includes installation of the missing fasteners.

Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : The remedy component includes the appropriate fasteners.

Identify How/When Recall Condition was Corrected in Production : The recall condition was corrected in production through work instructions and training.

Recall Schedule :

Description of Recall Schedule : Recall schedule will follow the 60 day requirement.

Planned Dealer Notification Date : NOV 02, 2023 - NOV 02, 2023

Planned Owner Notification Date : DEC 23, 2023 - DEC 23, 2023

* NR - Not Reported