

Date: 1/11/2024

In-Vehicle/In-App Communication – Safety Recall Reminder

NHTSA ID: 23V-755

Subaru Recall ID: WRQ23

Applicability: 2021 model year Crosstrek, 2024 model year Impreza, 2022 model year Forester, 2021-2023 model year Legacy, 2021-2023 model year Outback

Recall issue: Inhibitor switch replacement

Text:

Recall Description:	Subaru of America, Inc. (Subaru) has initiated a safety recall for certain 2021 model year Crosstrek vehicles, certain 2022 model year Forester, and certain 2021-2023 model year Legacy and Outback vehicles
Safety Risk Description:	The vehicles included in this recall may contain an inhibitor switch that was manufactured with an insufficient weld between the switch stator and cover which may allow water intrusion. Over time, moisture intrusion may cause the inhibitor switch to become inoperative. An inoperative inhibitor switch may result in the backup lamps not illuminating when in reverse gear, the rear-view monitor not displaying, the transmission gear select indicator in the instrument panel not being displayed, or inability to start the engine.
Remedy Description:	For all the potentially affected vehicles, Subaru dealers will replace the inhibitor switch with a new one at no cost to the customer. The recall repair procedure will be forthcoming in a subsequent subarunet announcement.