Part 573 Safety Recall Report

Manufacturer Name :	Forest River, Inc.
Submission Date :	NOV 17, 2023
NHTSA Recall No. :	23V-774
Manufacturer Recall No. :	34-1707

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

	2022-2024 Forest River Inc. Forester Class C Motorhomes BUSES, MEDIUM & HEAVY VEHICLES OTHER
Power Train :	
Descriptive Information :	The scope was determined using manufacturing records of when a change to the installation of the wiring began, to the week of November 17, 2023. 2022 FORESTER FRC2371AFT 2 2023 FORESTER FRC2371AFT 6 2024 FORESTER FRC2371AFT 2 Grand Total 10
Production Dates :	MAR 13, 2022 - NOV 06, 2023
VIN Range 1:	Begin : NR End : NR Not sequential



Number of potentially involved :

Estimated percentage with defect : 100 %

Population :

19

23V-774

art 573 Safe	ty Recall Report	23V-774	Page
		ass C Motorhomes	
Descriptive Information	: The scope was determined using manufaction installation of the wiring began, to the wee 2022 SUNSEEKER SSC2370AFT 2 2022 SUNSEEKER SSC2370FT 2 2023 SUNSEEKER SSC2370AFT 1 2023 SUNSEEKER SSC2370AFT 1 2024 SUNSEEKER SSC2370AFT 3 Grand total 9		e to the
Production Dates	. MAD 12 2022 NOV 06 2022		
VIN Range 1	: MAR 13, 2022 - NOV 06, 2023 : Begin : NR End : NI	R No	t sequential
VIN Range 1		R 🗌 No	t sequential
VIN Range 1 Description of Defect :		ve been wired to the house bat peration is locked out or allowe	tery
VIN Range 1 Description of Defect : Description of the Def	: Begin : NR End : NI ect : The park brake signal wire may not ha control center, where the slideroom op	ve been wired to the house bat peration is locked out or allowe	
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS	End: NR End: NI ect: The park brake signal wire may not ha control center, where the slideroom op depending on if the vehicle has the par S 1: NR S 2: NR	ve been wired to the house bat peration is locked out or allowe king brake engaged.	tery d
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS Description of the Safety R	: Begin : NR End : NI ect : The park brake signal wire may not ha control center, where the slideroom op depending on if the vehicle has the par S 1 : NR S 2 : NR isk : If a slideroom began extending during personal injury, property damage or let	ve been wired to the house bat beration is locked out or allowe king brake engaged. travel it may increase the risk o	tery d
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS Description of the Safety R Description of the Cat	Begin : NR End : NI ect : The park brake signal wire may not ha control center, where the slideroom of depending on if the vehicle has the par S 1 : NR S 2 : NR isk : If a slideroom began extending during personal injury, property damage or lease : Manufacturing error. The slideroom may extend.	ve been wired to the house bat beration is locked out or allowe king brake engaged. travel it may increase the risk o	tery d
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS Description of the Safety R Description of the Cat Identification of Any War that can Oc	Begin : NR End : NI ect : The park brake signal wire may not ha control center, where the slideroom of depending on if the vehicle has the par S 1 : NR S 2 : NR isk : If a slideroom began extending during personal injury, property damage or lease : Manufacturing error. The slideroom may extend.	ve been wired to the house bat beration is locked out or allowe king brake engaged. travel it may increase the risk o	tery d
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS Description of the Safety R Description of the Can Identification of Any War	: Begin : NR End : NI ect : The park brake signal wire may not ha control center, where the slideroom op depending on if the vehicle has the par S 1 : NR S 2 : NR isk : If a slideroom began extending during personal injury, property damage or le use : Manufacturing error. ning The slideroom may extend. cur :	ve been wired to the house bat beration is locked out or allowe king brake engaged. travel it may increase the risk o	tery d
VIN Range 1 Description of Defect : Description of the Def FMVS FMVS Description of the Safety R Description of the Safety R Identification of Any War that can Oc	Begin : NR End : NI ect : The park brake signal wire may not had control center, where the slideroom op depending on if the vehicle has the part S1 : NR S1 : NR S2 : NR isk : If a slideroom began extending during personal injury, property damage or lease : Manufacturing error. ning The slideroom may extend. cur : 1 : Wiring 12V	ve been wired to the house bat beration is locked out or allowe king brake engaged. travel it may increase the risk o	tery d

The information contained in this report was submitted pursuant to 49 CFR \$573

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology:

Manufacturing management found the concern during production the week of November 16, 2023, and contacted Forest Rivers Office of Corporate Compliance ("OCC") on November 16, 2023.

On November 17, 2023, Forest River's Corporate Recall Committee voted to recall.

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. An authorized Forest River Dealer or service center will need to perform the remedy. The signal wire will be installed to the battery control center.
	What is the Forest River Customer Service Phone Number? (574) 206-7600
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Forester & Sunseeker
	Forest River, Inc. Attn: WARRANTY MANAGER
	55135 CR 1
	Elkhart, IN 46514
How Remedy Component Differs from Recalled Component :	Affected Component – Wiring 12V PN N/A

The information contained in this report was submitted pursuant to 49 CFR §573

Page 4

	The signal wire will now be installed to the battery control center.
	During the week of November 17, 2023, the manufacturing plant began installing the brake signal wire to the battery control center.
Recall Schedule :	
Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date •	DEC 27, 2023 - DEC 27, 2023
Finitieu Deuter Hotmeution Dute .	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573