

November 29, 2023

Mr. Gerard Hones Mack Trucks, Inc. 7900 National Service Road Greensboro, NC 27409

Subject: Delay Returning to Engine Idle/FMVSS 124

Dear Mr. Hones:

This letter serves to acknowledge Mack Trucks, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MACK/ANTHEM (AN)/2023-2024 MACK/GRANITE (GR)/2023-2024 MACK/LR/2023-2024 MACK/TERRAPRO (TE)/2023-2024

Mfr's Report Date: November 22, 2023

NHTSA Campaign Number: 23V-792

Components: VEHICLE SPEED CONTROL

Potential Number of Units Affected: 851

Problem Description:

Mack Trucks, Inc. (Mack) is recalling certain 2023-2024 GR, AN, LR, and Terrapro vehicles. The engine may not return to idle within 2 seconds if the accelerator pedal position sensor becomes disconnected. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 124, "Accelerator Control Systems."

Consequence:

An engine that does not return to idle quickly enough can cause a loss of vehicle control, increasing the risk of a crash.

Remedy:

The remedy is currently under development. Owner notification letters are expected to be mailed January 21, 2024. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0455.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107DR 23V-792

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Mack Trucks, Inc.'s contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely,

Las Ande

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

