

MACK TRUCKS RECALL ALERT



Subject: Safety Recall SC0455, Accelerator Position Sensor, Cummins Engine
Recall Number: SRA-M455
Date: November 27, 2023
Applicable Markets: U.S. Canada Export

Description

The engine may not return to idle if the accelerator pedal position sensor becomes disconnected. An engine that doesn't return to idle could cause a loss of control and increase the risk of a crash.

There have been no field reports, warranty claims or customer complaints associated with this issue.

The remedy for this recall is currently under development.

Model and Model Years Affected

- Certain 2023 and 2024 Anthem, Granite, LR and TerraPro model vehicles manufactured October 24, 2022, through October 27, 2023.

Vehicle Quantities

- 947 vehicles (851 US, 96 Canada)

Dealer Responsibilities

- The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.
- Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal November 27, 2023.
- Owner notification letters will be released on or before December 15, 2023.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.