

**DEX Alert**

**Group:** Alerts / Recall

**Start Date:** 12/13/2023

**Removal Date:** 3/13/2024

**Title:** Safety Recall I-23-07 Released

**Alert Text:**

Indian Motorcycle has determined that some Model Year 2023-2024 Chieftain, Roadmaster, and Springfield motorcycles may have been built with an improperly routed crankshaft position sensor. This may cause the crankshaft position sensor to contact the front head pipe and result in a sensor failure and vehicle stall during operation, which increases the risk of a crash and serious injury.

To address this concern, Indian Motorcycle has released this safety recall with instructions to inspect and route the crankshaft position sensor correctly and replace if needed.

Click **HERE** to view I-23-07 Safety Recall

Click **HERE** to view FAQ