

Part 573 Safety Recall Report

23V-861

Manufacturer Name : Van Hool N.V.**Submission Date :** DEC 19, 2023**NHTSA Recall No. :** 23V-861**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Van Hool N.V.

Number of potentially involved : 64

Address : BERNARD VAN HOOLSTRAAT 58
LIER-KONINGSHOOIKT (BELGIUM) 00
B2500

Estimated percentage with defect : NR

Company phone : 999

Vehicle Information :

Vehicle 1 : 2024-2024 Van Hool CX45

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : The recall population is determined on the basis of information supplied by the component manufacturer FKT, which states, with a spreadsheet overview, that the recalled products differ from the production batch before and after the infected batch that occurred.

Production Dates : SEP 15, 2023 - NOV 29, 2023

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The attachment screw used to secure the pelvic restraint of the Type 2 seat belt assembly on the seats may break at any given time and/or under sudden impact.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Seat belt assembly can become disengaged from the seat while in service or on impact or crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported