2/9/24, 2:41 PM Federal Recall Bulletin

24PBB - Hendrickson COMPOSILITE® EXS20 Lift Axle Bearing Journals

Number

24PBB / NHTSA #: 24V043 / Transport Canada #: 2024-038 / Hendrickson Recall #: 23E-095

Supplier

Hendrickson

Description

Hendrickson COMPOSILITE® EXS20 Lift Axle Bearing Journals

Date

2/9/2024

What's New

Reference Hendrickson Recall 23E-095

Hendrickson alerted Peterbilt to a limited number of Hendrickson COMPOSILITE® EXS20 steerable, auxiliary lift axle suspension assemblies and individual steering knuckle assembly components that are equipped with bearing journals that may not have been seated correctly to the backbones of the left and right-side steering knuckle assembly components during manufacture.

Loss of oil from the respective axle hubs may cause the spindles to become loose from the steering knuckle assemblies or otherwise fracture and/or cause wheel end hub damage. This can further result in foreign object debris on the roadway, increasing the risk of a crash and/or injury.

Introduction

Safety Recall

Safety Recall

Reference Hendrickson Recall 23E-095

Hendrickson alerted Peterbilt to a limited number of Hendrickson COMPOSILITE® EXS20 steerable, auxiliary lift axle suspension assemblies and individual

2/9/24, 2:41 PM Federal Recall Bulletin

steering knuckle assembly components that are equipped with bearing journals that may not have been seated correctly to the backbones of the left and right-side steering knuckle assembly components during manufacture.

Loss of oil from the respective axle hubs may cause the spindles to become loose from the steering knuckle assemblies or otherwise fracture and/or cause wheel end hub damage. This can further result in foreign object debris on the roadway, increasing the risk of a crash and/or injury.

Situation

52 (51 US and 1 Canada) Model year 2024 389, 520, and 567 manufactured from 09/25/23 through 11/09/23 with Hendrickson COMPOSILITE® EXS20 steerable, auxiliary lift axle suspension assemblies.

Resolution

Safety Recall

Reference Hendrickson Recall 23E-095

Hendrickson bulletin will provide direction on:

- Inspection
- Repairs
- Parts
- Warranty Claims

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Warranty

Reference Hendrickson Recall 23E-095 to determine warranty eligibility and claim instructions.

Procedure

Reference Hendrickson Recall 23E-095 for any necessary inspection and/or repair procedures.

Parts

Reference Hendrickson Recall 23E-095 to determine any necessary parts related to this safety recall.

Links

24PBB - Chassis List

24PBB - US Customer Letter

24PBB - Canadian Customer Letter - English

24PBB - Canadian Customer Letter - French

LETTER FROM MANUFACTURER (HENDRICKSON) SENT TO CUSTOMERS

24PBB - HENDRICKSON Customer Letter