RECALL 24V045 / 2024-041 REMEDY INSTRUCTIONS



Make(s): CLIPPER & VIKING

Model(s): CWT9000ROK & VWT9000ROK

Model Year(s): 2024

Concern:

The tail lamp bezel that is rated for reflectivity may not have been installed around the tail lamps as required.

Repair Code: RC-058-03-00-004485

Allotted Time: .30 HRS. Inspection Code: N/A Allotted Time: N/A

Photo(s) Required: YES, POST REMEDY

Prior Authorization Required: YES Part(s) Kit Number: F100510960

Part(s) Return: N/A

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

ORDER PARTS KIT: F100510960, REAR TAIL LAMP BEZEL WITH REFLECTIVE PROPERTIES

STEP 1: LOCATE THE TAIL LAMPS ON THE REAR OF THE VEHICLE;

STEP 2: INSTALL ONE TAIL LAMP BEZEL PER TAIL LAMP;

• IF NEEDED, UNSCREW THE TAIL LAMP AND MOVE DOWN NOT MORE THAN 1/4";

STEP 3: INSTALL TAIL LAMP BEZEL;

STEP 4: TAKE A PHOTO OF THE ENTIRE REAR OF THE VEHICLE WITH THE INSTALLED BEZELS;

STEP 5: SUBMIT PHOTO AND CLAIM REPAIR CODE.