

STOP SALE NOTICE



SERVICE CAMPAIGN: 001062

FR ID: 120-1729

January 26, 2024

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

Pursuant to Federal Motor Vehicle Safety Act; 49 CFR Part 573.11; this notice shall serve as a formal

SAFETY RECALL - STOP SALE NOTIFICATION.

CERTAIN 2024 CLIPPER AND VIKING TRAVEL TRAILERS

Forest River has decided that a noncompliance, which relates to the motor vehicle safety, exists in certain 2024 Viking and Clipper Travel Trailer Recreational Vehicles and fail to comply with the requirements of *Federal Motor Vehicle Safety Standard* (FMVSS) number 108 - Lamps, reflective devices, and assoc. Equipment Additionally, this non-compliance fails to meet the requirements of Canadian *Motor Vehicle Safety Regulations* (CMVSS) number 108 - Lamps, reflective devices, and assoc. Equipment. This is to inform you that your vehicle may be non-compliant with the requirements of the *Motor Vehicle Safety Regulations* and that the non-compliance could affect the safety of a person. Forest River is issuing a Stop Sale Notice effective immediately. The tail lamp bezel that is rated for reflectivity was not being consistently installed on the vehicles. An approaching vehicle from the rear may not get the proper indication of conspicuity from the suspect vehicle, which may result in a crash. Additionally, the taillamps do not meet FMVSS 108.

Please access your Home Page on Dealer Connect to verify if your Dealership has units in stock that are subject to this recall. Enter the Service Campaign number referenced above in the “Campaign Search” field, click on the “Campaign ID Number”. Next, select “MY VINS”. Not all Dealers have units in stock that are affected by this recall.

DEFECT/NONCOMPLIANCE:

The tail lamp bezel that is rated for reflectivity was not being consistently installed on the vehicles.

EVALUATION OF RISK:

An approaching vehicle from the rear may not get the proper indication of conspicuity from the suspect vehicle, which may result in a crash. Additionally, the taillamps do not meet FMVSS 108.

SERVICE PROCEDURE:

Remedy is under development.

HELPFUL CONTACT INFORMATION:

CONTACT	PHONE
CUSTOMER SERVICE	(269) 467-4600