

June 30, 2016

00407-01886 Version 11

## Safety Recall: Front Passenger's Airbag Inflator May Produce Excessive Pressure After Long-Term Exposure To High Absolute Humidity

Supersedes 14-070, dated June 14, 2016 to change failed part numbers for Element and Odyssey that are highlighted in **yellow**

This bulletin is replaced by S/B 16-047, Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized (Phase 1)

If you did Service Bulletin 14-070 on or before June 13, 2016. Make sure to use Warranty Claim Information provided below.

### WARRANTY CLAIM INFORMATION

- **For 2002-04 CR-Vs only:** If you did the repair in this S/B on or before December 19, 2015 (RO date), use the Warranty Claim Information provided below. Any repairs after December 19, 2015, refer to S/B 15-067, *Safety Recall: Front Passenger's Airbag Inflator Can Be Over-Pressurized*.
- **The Accord and Civic warranty information is included in case you opened an RO on or before June 14, 2015.** Refer to S/B 15-041 for any repairs made after that date.

### Replacing the front passenger's airbag inflator

Year/Model	Operation Number	Replacement Part number	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
2003 Accord	7541B0	04785-SDA-307	0.7 hr	5KN00	JL800	14-070Z	06780-SDN-A90ZA
		04790-SDA-308	0.7 hr	5KN00	JL800	14-070Y	06780-SDN-A90ZA
2004-05 Accord	7541B0	04785-SDA-306	0.7 hr	5KN00	JL800	14-070X	06780-SDN-A90ZA
2001-05 Civic	7541B0	04785-S5A-307	0.7 hr	5KN00	JL900	14-070W	06780-S5A-A80ZA
2001-04 Civic GX							
2003-05 Civic Hybrid		04790-S5A-308	0.7 hr	5KN00	JL900	14-070V	06780-S5A-A80ZA
2002-04 CR-V	7541B0	04785-S9A-307	0.7 hr	5KN00	JM000	14-070U	06780-S9A-A80ZA
		04790-S9A-308	0.7 hr	5KN00	JM000	14-070T	06780-S9A-A80ZA
2005 CR-V	7541B0	04785-S9A-306	0.7 hr	5KN00	JM000	24-070A	06780-S9A-A80ZA
		04790-S9A-305	0.7 hr	5KN00	JM000	24-070B	06780-S9A-A80ZA
		04790-S9A-315	0.7 hr	5KN00	JM000	24-070C	06780-S9A-A80ZA

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

2003–04 Element	7541B0	04785-SCV-307	0.8 hr	5KN00	JM100	24-070D	06780-SCV-A80ZA
		04790-SCV-308	0.8 hr	5KN00	JM100	24-070E	06780-SCV-A80ZA
		04790-SCV-318	0.8 hr	5KN00	JM100	24-070F	06780-SCV-A80ZA
2002 Odyssey	7541B1	04785-S0X-307	0.7 hr	5WX00	JM200	24-070G	06780-S0X-A70ZA
		04790-S0X-308	0.7 hr	5WX00	JM200	24-070H	06780-S0X-A70ZA
		04790-S0X-318	0.7 hr	5WX00	JM200	24-070I	06780-S0X-A70ZA
2003–04 Odyssey	7541B1	04785-S0X-306	0.7 hr	5WX00	JM200	24-070J	06780-S0X-A70ZA
		04790-S0X-305	0.7 hr	5WX00	JM200	24-070K	06780-S0X-A70ZA
		04790-S0X-315	0.7 hr	5WX00	JM200	24-070L	06780-S0X-A70ZA
2003–04 Pilot	7541B1	04785-S9V-307	0.8 hr	5WX00	JM300	24-070M	06780-S9V-A81ZC
		04790-S9V-308	0.8 hr	5WX00	JM300	24-070N	06780-S9V-A81ZC
		04790-S9V-318	0.8 hr	5WX00	JM300	24-070P	06780-S9V-A81ZC
2005 Pilot	7541B1	04785-S9V-306	0.8 hr	5WX00	JM300	24-070Q	06780-S9V-A81ZC
		04790-S9V-305	0.8 hr	5WX00	JM300	24-070R	06780-S9V-A81ZC
		04790-S9V-315	0.8 hr	5WX00	JM300	24-070S	06780-S9V-A81ZC
2006 Ridgeline	7541B1	04785-SJC-307	0.7 hr	5WX00	JM400	24-070T	77820-SJC-A00ZA
		04790-SJC-308	0.7 hr	5WX00	JM400	24-070U	77820-SJC-A00ZA
		04790-SJC-318	0.7 hr	5WX00	JM400	24-070V	77820-SJC-A00ZA

Skill Level: Repair Technician