



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

May 9, 2017

Mr. John Kobylarz
Automotive Safety Office
Jaguar Land Rover North America, LLC
555 MacArthur Boulevard
Mahwah, NJ 07430

NEF-150TB
17V-286

Subject: Fuel Return Hose may Leak

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

JAGUAR/XE/2017

Mfr's Report Date: April 27, 2017

NHTSA Campaign Number: 17V-286

Components:

FUEL SYSTEM, DIESEL

Potential Number of Units Affected: 7

Problem Description:

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2017 XE vehicles equipped with a 2.0L diesel engine. The vehicles have a fuel return hose that may leak.

Consequence:

A diesel fuel leak onto the road surface may cause a skid hazard, increasing the risk of a crash. If the fuel leak contacts a hot engine or exhaust component, there would be an increased risk of a fire.

Remedy:

Jaguar will notify owners, and dealers will replace the fuel return hose, free of charge. The recall is expected to begin June 19, 2017. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H016.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:


You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the affected fuel return hose.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read 'Jennifer Timian', with a date '1/21/16' written at the end of the signature.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement