



SAFETY RECALL H056 / N124 - UPDATE

SERVICE ALERT

16-NOV-17

NO.: JA17RE-03
SA17RE-02

SEC.: RECALL

MKT.: CAN / USA

Please be advised that SAFETY RECALLS H056 and N124, *Virtual Instrument Cluster Goes Blank*, have been relaunched with immediate effect.

SAFETY RECALL H056 repairs may commence on all affected 2018MY Jaguar F-PACE, XE, and XF vehicles. Affected 2017MY XJ vehicles are also now able to be repaired.

Affected 2016MY XJ and 2017MY F-PACE and XF vehicle repairs remain on hold pending the publication of an updated Technical Bulletin containing the repair procedure for these vehicles.

SAFETY RECALL N124 repairs may commence on all affected 2017MY Land Rover Range Rover Sport and Range Rover vehicles.

Technical Bulletins **H056NAS2** and **N124NAS2** have been published to TOPIx. Technicians must carefully review all new, highlighted Cautions and Notes within the Diagnostic Procedures for all vehicles, with particular attention to the Symptom Driven Diagnostics (SDD) procedure for 2017MY XJ vehicles.

A revised Safety Recall launch timing plan for model and model year is attached.

For questions regarding the content of this publication, please contact:
Alan Clarke Product Investigation - Critical Concerns Specialist
201-818-8373 aclark43@jaguarlandrover.com

Jaguar Land Rover North America, LLC
555 MacArthur Boulevard
Mahwah, NJ 07430



SAFETY RECALL H056 / N124 - PROGRAM LAUNCH TIMING

Vehicle Line	Tool Type	2-Hour Repair	Special App Repair (approx. 10 mins)	Program Launch
17MY Range Rover Sport, Range Rover	PATHFINDER	Now available	Due 22 NOV	Relaunched 16 NOV - see TOPIX
18MY F-PACE, XE, XF	PATHFINDER	Now available	Due 22 NOV	Relaunched 16 NOV - see TOPIX
17MY XJ	SDD	Now available with Manual Patch	TBA	Launched 16 NOV - see TOPIX
16MY XJ	SDD	TBA	TBA	TBA
17MY F-PACE, XF	SDD	Not planned	Due 7 DEC	7 DEC