

Honda Recall Notification
2015 Model Year Acura TLX
9AT Sensor Cluster Terminal Crimp

REVIEWED BY:
JOHN TURLEY
SEP-6-2016
John Turley

Submit to NHTSA – September 6, 2016

Since filing the original Defect Information Report (NHTSA ID 16V-640) on September 1, 2016, Honda has finalized the VIN range, the dates of manufacture, and the total number of potentially affected vehicles involved in this recall. The identification of potentially affected vehicles and the total number of potentially affected vehicles are being amended to reflect this update.

573.6(c)(2)

Identification of potentially affected vehicles: see below for VIN range and date of manufacture updates.

<u>Make/Model</u>	<u>Previous VIN Range/Dates of Manufacture</u>	<u>New/Current VIN Range/Dates of Manufacture</u>
Acura TLX 2WD	TBD	19UUB2F51FA000068 - 19UUB2F51FA009448 June 17, 2014 to October 22, 2014
Acura TLX 4WD	TBD	19UUB3F76FA000056 - 19UUB3F51FA003588 June 17, 2014 to December 12, 2014

573.6(c)(3)

Total number of potentially affected vehicles: see below for population updates.

<u>Previous Population</u>	<u>New/Current Population</u>
TBD	8,354