

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers, Parts Managers

FROM: Gregory Gunther, Department Manager, Vehicle Compliance and Analysis, Engineering Services

RE: [Service Campaign Launch Notification](#)
Sliding Roof – Car Wash Mode
MY20 167(GLS-Class)

Date: May 22, 2020

IMPORTANT NEW SERVICE CAMPAIGN LAUNCH INFORMATION

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Campaign No. :	Campaign Desc. :	Sliding Roof – Car Wash Mode
2020050010	20P5490417	
<p>This is to notify you of a Service Campaign launch regarding the sliding roof – car wash mode - on 8 Model Year (“MY”) 2020 X167 (GLS-Class) vehicles. This service campaign is related to PENDING RECALL NHTSA ID#20V264. Affected VINs will be flagged in VMI as "OPEN" on May 22, 2020.</p>		
Background		
Issue	Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year (“MY”) 2020 GLS-class vehicles (X167 platform), the sunroof control unit software may not meet current production specifications. There is no safety risk.	
What We’re Doing	MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will update the control unit software on the affected vehicles.	
Parts	Parts are not necessary for this Service Campaign.	
Vehicle Model Year(s)	2020	
Vehicle Model	GLS-Class	
Vehicle Populations		
Total Campaign Population	8	
Next Steps/Notes		
AOMS/SOMS	<p>AOMs – This Service Campaign may generate questions from your dealers.</p> <p>IMPORTANT: After warranty claim submission for this service campaign, VINs currently in “pending” status will be automatically removed from the recall (NHTSA ID# 20V264) population within a minimum of 7 business days in Netstar VMI. Please allow time for the systems to accept the claim and change the status accordingly.</p>	
<p>While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.</p>		



Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2020050010, May 2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model GLS-class vehicles (X167 platform)**
Model Year 2020

Sliding Roof – Car Wash Mode

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year (“MY”) 2020 GLS-class vehicles (X167 platform), the sunroof control unit software may not meet current production specifications. There is no safety risk. An authorized Mercedes-Benz dealer will update the control unit software on the affected vehicles.

Prior to performing this Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired. Always Check VMI for any open campaigns, and perform accordingly.
- **VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.**
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 8 vehicle is affected.

Order No. P-SC-2020050010

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

i Note:

- Use Xentry 12/19 with all associated patches or higher.
- Follow the steps exactly as described in Xentry.
- Connect battery charger (battery voltage  >12.5V).
- Ensure all electrical consumers are switched-off.
- In the event of software/SCN update issues, contact Star Diagnosis User Help Desk via. XSF ticket.
- Refer to Star Diagnosis System (SDS) Best Practices Guide.

Work procedure

1. Connect XENTRY Diagnosis.
2. Perform SCN coding in A98 panorama sliding roof control unit.

i To do this, select menu item "Quick test view  A98 control module 'Panorama Sliding Roof' (PSD)  Adaptations  Control unit update  Update of SCN coding".

i Then follow the user guidance in XENTRY Diagnosis.

3. Disconnect XENTRY Diagnosis.

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
Star Diagnosis System (SDS), Connect/disconnect (02-4762)
Perform SCN coding in A98 panorama sliding roof control unit (02-9446)

Damage Code	Operation Number	Labor Time (hrs.)
54 904 17 8	02-5058	0.1
	02-4762	0.1
	02-9446	0.1

i Note

Operation Number labor times are subject to change