

U.S. Department of Transportation

National Highway Traffic Safety Administration

April 28, 2017

Mr. R. Thomas Brunner Dept Manager VCA Mercedes-Benz USA, LLC. 1 Mercedes Drive Montyale, NJ 07645

17V-252

NEF-150TB

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Steering Coupling Bolt may be Loose

Dear Mr. Brunner:

This letter serves to acknowledge Mercedes-Benz USA, LLC.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES BENZ/C250/2013-2014 MERCEDES BENZ/C300/2013-2014 MERCEDES BENZ/C350/2013 MERCEDES BENZ/C63/2013 MERCEDES BENZ/GLK250/2013-2014 MERCEDES BENZ/GLK350/2013-2015

Mfr's Report Date: April 12, 2017

NHTSA Campaign Number: 17V-252

Components: STEERING

Potential Number of Units Affected: 168

Problem Description:

Mercedes-Benz USA LLC. (MBUSA) is recalling certain 2013-2014 C250, C300 4MATIC, GLK250 4MATIC BLUETEC and GLK350 vehicles, 2013 C250 Coupe, C350, C350 4MATIC Coupe, C350 Coupe and C63 AMG Coupe vehicles, and 2013-2015 GLK350 4MATIC vehicles. The steering coupling connecting bolt may have been insufficiently tightened, possibly resulting in a loss of steering.

Consequence:

A loss of steering can increase the risk of a crash.

Remedy

MBUSA will notify owners, and dealers will inspect the steering coupling connecting bolt, tightening it as necessary, free of charge. The recall is expected to begin in May 2017. Owners may contact MBUSA customer service at 1-800-367-6372.



Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received MBUSA's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Tariq Bond who may be reached by phone at 1-202-366-5472, or by email at tariq.bond@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

