

IMPORTANT SAFETY RECALL

STOP RETAIL SALES and DELIVERY

Suzuki Motor Corporation has determined that a safety defect exists in the following models:

Model	Starting VIN	Ending VIN
LT-A750XCL6	5SAAR41A_G7100809	5SAAR41A_G7101260
LT-A750XL6	5SAAR41A_G7100721	5SAAR41A_G7101380
LT-A750XPCL6	5SAAR41P_G7101461	5SAAR41P_G7103885
LT-A750XPL6	5SAAR41P_G7101381	5SAAR41P_G7103520
LT-A750XPZL6	5SAAR41P_G7101511	5SAAR41P_G7103900
LT-A750XCL7	5SAAR41A_H7100355	5SAAR41A_H7100780
LT-A750XL7	5SAAR41A_H7100001	5SAAR41A_H7100764
LT-A750XPCL7	5SAAR41P_H7100389	5SAAR41P_H7101370
LT-A750XPL7	5SAAR41P_H7100001	5SAAR41P_H7101539
LT-A750XPZL7	5SAAR41P_H7100505	5SAAR41P_H7101355
DL650AL2	JS1VP56A_C2100176	JS1VP56A_C2104577
DL650AL3	JS1VP56A_D2100007	JS1VP56A_D2102764
DL650AL4	JS1VP56A_E2100004	JS1VP56A_E2102412
DL650AAL4	JS1VP56A_E2100006	JS1VP56A_E2102393
DL650AL5	JS1VP56A_F2100010	JS1VP56A_F2101746
DL650AAL5	JS1VP56A_F2101836	JS1VP56A_F2102122
DL650XAL5	JS1VP56A_F2101268	JS1VP56A_F2103416
DL650AL6	JS1VP56A_G2100025	JS1VP56A_G2101103
DL650XAL6	JS1VP56A_G2100154	JS1VP56A_G2101201

Suzuki Motor Corporation has initiated a safety recall campaign to replace the stator assembly. The generator stator may have insufficient heat resistance due to the assembly process, which can lead to a short circuit of the stator wires. A short circuit of the stator wires causes lower electricity generation and reduced battery charging, which can cause the engine to stop running and be unable to be restarted. To ensure customer safety and satisfaction, dealers will replace the stator assembly.

SALES



Way of Life!

MOTORCYCLE / ATV Division

Bulletin No: 16-172

Date: November 28, 2016

Technical Service Bulletin:

Service information regarding this safety recall will be available in a Technical Service Bulletin the week of December 12, 2016.

Parts Availability:

Parts to perform this recall campaign will be available beginning the week of December 12, 2016

Customer Notification:

Retail customers will be notified of this safety recall beginning approximately the week of December 19, 2016.

Consequences of Non-Compliance:

ALL NEW SUZUKI VEHICLES IN DEALER INVENTORY THAT ARE SUBJECT TO A RECALL OR CUSTOMER SATISFACTION CAMPAIGN INITIATED BY SUZUKI MOTOR OF AMERICA, INC. ("SMAI") MUST BE REPAIRED BEFORE THESE VEHICLES ARE SOLD OR DELIVERED BY THE DEALER TO THE RETAIL CUSTOMER. FAILURE TO DO SO IS A VIOLATION OF FEDERAL LAW, THE SUZUKI POWERSPORTS DEALER SALES AND SERVICE AGREEMENT (THE "DEALER AGREEMENT"), AND SMAI'S SALES POLICY REGARDING FACTORY SAFETY RECALL OR SAFETY MODIFICATION PROGRAMS (THE "POLICY"). A COPY OF THE POLICY IS AVAILABLE ON SUZUKI CONNECT FOR YOUR REFERENCE.

FURTHER, FAILURE TO COMPLY WITH THE INSTRUCTIONS OF SMAI REGARDING COMPLIANCE WITH RECALLS OR OTHER SAFETY OR PRODUCT IMPROVEMENT CAMPAIGNS OR PROGRAMS, AND/OR FAILURE TO MAKE A GOOD FAITH EFFORT TO COMPLY WITH THE FEDERAL CLEAN AIR ACT, THE NATIONAL TRAFFIC AND MOTOR VEHICLE SAFETY ACT, THE CONSUMER PRODUCT SAFETY ACT, OR ANY OTHER LAWS, ORDERS, RULES, OR REGULATIONS REGARDING RECALLS OR OTHER SAFETY OR PRODUCT IMPROVEMENT CAMPAIGNS OR PROGRAMS CONSTITUTES A BREACH OF THE SUZUKI POWERSPORTS DEALER SALES AND SERVICE AGREEMENT AND IS A VIOLATION OF SMAI'S SALES POLICY REGARDING FACTORY SAFETY RECALL OR SAFETY MODIFICATION PROGRAMS. A DEALER MAY BE HELD RESPONSIBLE FOR ANY PRODUCT DAMAGE AND/OR PERSONAL INJURIES RESULTING FROM SUCH FAILURE.

If you need any additional information, please contact the Suzuki Techline or your Technical Service Manager at 714-996-7480. We apologize for this inconvenience and will do everything possible to resolve this situation as quickly as possible.

Thank you for your continued support and understanding.

A handwritten signature in black ink that reads 'Bruce Knight'.

Bruce Knight
National Motorcycle/ATV Sales Manager