

## Fuel tank replacement Your Lamborghini Murciélago LP640 with chassis number: «VIN» Santa Monica,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Automobili Lamborghini SpA has decided that a defect, which relates to motor vehicle safety, exists in the model year 2007-2008 Murciélago (version LP640).

Lamborghini has determined that it is possible for welds holding the fuel pump support inside the fuel tank of the model year 2007-2008 Murciélago Coupè and Roadster (version LP640) to detach. This situation, though rare, may result in a slow fuel leak which could potentially result in a fire only if an external ignition source is present.

For safety reasons it is therefore necessary to repair these vehicles.

## Your vehicle is one of the models affected.

Please contact an authorized Lamborghini dealer immediately to arrange an appointment. Please bring this letter and your Service Booklet with you when you visit the dealer, so that we can complete all of the necessary documentation.

If you detect the odour of fuel or observe fuel on the ground, please contact your Lamborghini dealer to get your vehicle towed to service.

Your dealer will replace the fuel tank, which will take a maximum of 2 business days. This work will, of course, be carried out at no charge to you.

Any Lessor that receives this notification must send a copy of this notice to the Lessee.

Automobili Lamborghini America LLC



If you have any queries regarding this measure please contact your Lamborghini dealer, or Automobili Lamborghini LLC at the following phone numbers:

Tel: +1-912-409-5634

+1-508-808-9562

Fax: +1-310-664-4975

Any owner who has already incurred costs to repair the problem addressed by this recall, will be reimbursed by Automobili Lamborghini. This includes all customer payments toward fuel tank replacements on affected vehicles prior to this recall (other than those caused by accident or abuse). Contact your Lamborghini dealer for the reimbursement and present the invoice demonstrating the fuel tank replacement.

We are sure you will appreciate the need for this precautionary measure, and we regret any inconvenience caused by the extra service visit.

If you have sold your vehicle or have taken it out of service, please complete the enclosed reply sheet and return it to us by fax as soon as possible.

Your cooperation in this matter will be appreciated.

Yours sincerely,

Wolfgang Hoffmann Chief Operating Officer

Automobili Lamborghini America LLC

Renè Sueltzner Head of After Sales

René Suettern

Automobili Lamborghini America LLC



Automobili Lamborghini America LLC
Customer Service and Spare Parts
Fax: +1-310-664-4975
REPLY SHEET:
Vehicle Identification Number:
Vehicle cannot be checked because it has been:
□ scrapped □ stolen
_ stolen
sold to a domestic buyer
□ sold to an overseas buyer
to following new address:
Last Name:
First Name:
Street: No.:
110
ZIP Code: City:
Country:

Date / Signature: