



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., P.O. Box 2215
Torrance, CA 90509-9870

This notice applies to your vehicle:

March 2016

RE: 2014–15 RLX
NHTSA Recall 14V-792

IMPORTANT

- **Your vehicle is included in a safety recall and should have the recall service done as soon as possible.**
- **Any authorized Acura dealer will perform the recall service at no charge to you.**

Dear

What is the reason for this notice?

Our records indicate that a SAFETY RECALL has not been completed on this vehicle; refer to the address card for the affected VIN. The headlight reflector material may not be properly adhered, allowing it to peel off of the reflector, and affect headlight performance and your ability to see at night, which increases the risk of a crash.

What should you do?

Please contact any authorized Acura dealer to schedule a service appointment. The dealer will replace both the left and right headlight assemblies. This work will be done *free of charge*.

If you have questions

If you have any questions about this notice, or you need assistance locating a dealer, you may contact Acura Automobile Client Relations at 1-800-382-2238, option 4. You may also find this information at *Acura.com*.

We apologize for any inconvenience this safety recall may cause you. We are taking this action in the interest of your safety and continued satisfaction with your Acura vehicle.

Sincerely,

**American Honda Motor Co., Inc.
Acura Automobile Division**

NOTICE: If this is a leased vehicle, please forward this notice to the lessee.

Marzo del 2016

Esta notificación aplica a su vehículo:

RE: RLX 2014–2015
Campaña de seguridad NHTSA 14V-792

IMPORTANTE

- **Su vehículo está incluido en una campaña de seguridad y debe completar el servicio de la campaña lo más pronto posible.**
- **Cualquier concesionario autorizado Acura podrá realizar el servicio de la campaña de seguridad, sin costo alguno para usted.**

Estimado

¿Cuál es el motivo de ésta notificación?

Nuestros registros indican que no se ha completado una CAMPAÑA DE SEGURIDAD en este vehículo; consulte la tarjeta de dirección para ver el VIN afectado. El material reflector de las luces principales puede que no esté adherido adecuadamente ocasionando que se desprege del reflector y afecte el desempeño de las luces principales y su habilidad para ver en la noche, aumentando el riesgo de un choque.

¿Qué debe hacer?

Por favor comuníquese con cualquier concesionario autorizado Acura para programar una cita de servicio. El concesionario reemplazará ambos conjuntos de luces principales, el izquierdo y el derecho. Este trabajo se realizará *sin costo alguno*.

Si tiene preguntas

Si tiene alguna pregunta acerca de ésta notificación o necesita asistencia para ubicar un concesionario, puede comunicarse con Relaciones con el cliente de automóviles Acura al 1-800-382-2238 y seleccione la opción 4. Usted también puede encontrar esta información en *Acura.com*.

Le pedimos disculpas por cualquier inconveniente que esta campaña de seguridad pudiera causarle. Nosotros estamos tomando esta acción en el interés de su seguridad y satisfacción continua con su vehículo Acura.

Atentamente,

American Honda Motor Co., Inc.
División Automotriz de Acura

AVISO: Si este es un vehículo arrendado, por favor envíe esta notificación al arrendatario.

PARA USO DEL CONCESIONARIO SOLAMENTE: REFERENCIA BOLETÍN DE SERVICIO #14-051
JN2