

45797	Some 2013-2017 Escape and 2015-2017 MKC vehicles may exhibit a vibration attributed to the tires. Prior to performing any road force balancing procedures or related diagnosis, ensure the vehicle is driven a minimum of 15 miles to eliminate any possible flat spotting conditions and potential misdiagnosis. Refer to Workshop manual, section 204-04A for further information. In addition, it is recommended that diagnosis of tire/wheel vibration should not be performed on tires with less than 320 KM (200 miles). Some initial tire/wheel vibration issues (such as flat spotting) may correct themselves after the tires have been in service for 320 KM (200 miles).
-------	---