

SSM
46720

Some 2016 F-150 vehicles may exhibit the off-road display flickering in the IPC. Reprogram the IPC using Integrated Diagnostic System (IDS) release 106.03 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at www.motorcraftservice.com. For claiming, use causal part 10849 and applicable labor operations in section 10 of the service labor time standards (SLTS) manual.