

SSM
47249

Some 2018 EcoSport vehicles equipped with remote start may exhibit an intermittent remote start/stall condition during the first remote start attempt. The vehicle should remote start normally after the second attempt. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.