	Some 2017-2018 Continental and 2018 Navigator vehicles may exhibit an outside front seat bolster
SSM	support bracket that is broken or cracked. The outside front seat bolster support bracket is now
47403	available as a separate service part. Base part number 9960328. When ordering, please refer to the
	parts catalog for the VIN specific application.