| | Some 2018 EcoSport vehicles equipped with remote start may exhibit an intermittent remote |
|-------|--|
| | start/stall condition during the first remote start attempt. Some 2018 EcoSport vehicles equipped with |
| SSM | perimeter plus security and intelligent access (IA) with push button start may exhibit a false security |
| 47434 | trigger upon opening the rear tailgate while the system is armed. For vehicles exhibiting either concern, contact the supplier technical support at 1-800-FORDKEY (1-800-367-3539) for assistance. |
| | |