	Some 2014-2018 Escape vehicles may exhibit a concern of not able to program and/or no electrical
SSM	power after installation of a service part BCM. Inspect the BCM for the presence of fuse F88. If the
47508	fuse is missing, install the correct size replacement fuse as outlined in the Wiring Manual and then
	re-evaluate the concern.