

SSM 47672

Some 2017-2019 F-Super Duty vehicles may exhibit a headliner edge that shows around the overhead console. Using a trim stick or other suitable tool, the headliner should be tucked back in without replacement of the entire headliner.