

SSM 47680	Some 2018 EcoSport vehicles equipped with a 1.5L Duratorq-TDCi engine may exhibit an illuminated MIL with DTC P061B. The 2018 Powertrain Controls/Emission Diagnosis (PC/ED) Diesel Manual, Section 4 is incorrect and a powertrain control module (PCM) replacement may not be necessary for this DTC. The PC/ED is in the process of being updated. Do not replace the PCM at this time. Engineering is investigating, monitor OASIS for updates.
-----------	---