

SSM 47696	Some 2017-2018 F-150 vehicles equipped with a 2.7L EcoBoost engine may exhibit excessive white or blue smoke from the exhaust at start up after a cold soak. If there is no associated oil consumption concern and no drivability symptoms present, do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.
-----------	---