| SSM 47771 | Some 2019 Escape/Fusion vehicles equipped with a Sony branded audio system may exhibit AM |
|-----------|---|
| | presets that may not save and/or may be lost after an ignition cycle. Do not attempt any repairs at |
| | this time. Engineering is investigating, monitor OASIS for updates. |