

MFR Communication ID	MFR Communication Date	Make (Brand)	Model	Model Year	Text
SSM 47863	3/15/2019	Ford	Transit Connect	2019	Some 2019 Transit Connect vehicles produced on or before 17-Dec-2018 and equipped with 4G Wi-Fi without SYNC, may exhibit a Wi-Fi Hotspot button not showing in the menu. To correct this condition, perform programmable module installation (PMI) on the audio control module (ACM) and when asked if the original module is installed select NO. This procedure will retrieve the updated as-built from the database and install it into the module. For claiming, use causal part 18C869 and applicable