

SSM 47836	Some 2011-2019 F-Super Duty 6.7L diesel equipped vehicles may exhibit a ticking/tapping noise traced to the reductant injector. This noise is not an indication of incorrect injector function and has no short or long term durability effects on the component. If the vehicle does not exhibit any drivability related symptoms or diagnostic trouble codes (DTC) do not attempt repairs.
-----------	--