

SSM 48005 - 2015-2017 Transit - Driveshaft And Transmission Output Flange Service Strategy Change

If a 2015-2017 Transit vehicle originally equipped with a rubber flexible coupling requires replacement of the driveshaft assembly and/or transmission output flange, refer to the parts catalog supersession information for a complete list of the required parts. The service strategy has changed, and these repairs must now be completed by installing a new driveshaft and transmission output flange coupled with a u-joint.