

SSM 48361 - 2017 Expedition - Warning Lamp On - Greater Than 120 Km/h (75 MPH) Overspeed Illuminated In The Instrument Panel Cluster (IPC)

Some 2017 Expedition vehicles may exhibit a greater than 120 Km/h (75 MPH) overspeed warning in the IPC even though the vehicle has not hit that speed. This may be due to a software error in the cluster. To correct this condition, perform a software update to the IPC using the appropriate Ford diagnostic scan tool. For claiming, use causal part 10849 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.