

## **SSM 48989 - 2017-2019 Explorer/Police Interceptor Utility - Noise While Turning**

Some 2017-2019 Explorer/Police Interceptor Utility vehicles may exhibit various noise concerns while turning. Workshop Manual (WSM), Section 211-02 Power Steering > Diagnosis and Testing has been updated with improved information to aid with accurate noise diagnosis. Replacing the steering gear may not necessarily eliminate the noise concern. Use Chassis Ears on all suspected components to accurately diagnose noise concerns.

APPLICABLE VEHICLES  
2017 - 2019 TRUCK: UB U502N EXPLORER