

SSM 49152

Title:

2018-2019 EcoSport - Auto Lock Feature Disabled - Built On Or Before 01-Jul-2019

Some 2018-2019 EcoSport vehicles built on or before 01-Jul-2019 may have the auto lock feature disabled. To enable this feature, use the FDRS scan tool and reprogram the body control module (BCM). For claiming, use causal part 15604 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

Vehicles:

2018-2019 EcoSport B515 India (BW)