

## **SSM 49244: 2015-2020 Mustang - No Horizontal Adjustment Of Front Power Seats - Power Seat Track Motor Inoperative**

Some 2015-2020 Mustang vehicles may exhibit a concern of no horizontal movement of the front power seats. This may be caused by a defective seat track motor or separation of the drive motor cable from the seat track. The seat track motor assembly is available separately (14547) and replacement of the complete seat frame assembly (9661711) may not be required. Refer to Workshop Manual, Section 501-10A for seat track motor removal.

### **Vehicles:**

2015-2020 Mustang (S550) (ZG)