

SSM 49303 - 2015-2020 Mustang - Rear Seat Cover Loose And/Or Foam Exposed

Some 2015-2020 Mustang vehicles may exhibit a concern of the rear seat cover appearing loose or having the foam underneath the seat cover exposed. This condition is most apparent at the front outer corners of the lower seat cushion. This may be due to the seat cover coming loose. This can be corrected by tucking the corners of the seat cushion underneath the seat cover. Any loose seat cover material can also be tucked under the cover. Replacement of the seat cushion cover is not necessary to correct this condition.

APPLICABLE VEHICLES

2015 - 2020 CAR: ZG S550N MUSTANG