

SSM 49602 - 2021 F-150 - Console Gear Shift Lever Will Not Come Out Of Park Position - GearShift Lever Stow Position Operation Delayed Or Stuck

Some 2021 F-150 vehicles built on or before 29-Jan-2021 and equipped with a console gear shift lever may exhibit a condition where the gear shift lever is unable to come out of the park position. Some vehicles may also exhibit the gear shift lever stow function is delayed or inoperative. This may be due to software in the gearshift module (GSM). To correct the condition, reprogram the GSM. For claiming, use causal part 7210 and applicable labor times in section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2021 TRUCK: FD P702N F150