

## **SSM 49689: 2017-2020 Lincoln Continental - Belt Minder Enable/Disable**

Some 2017-2020 Lincoln Continental vehicles may exhibit a concern where the belt minder is difficult to activate/deactivate. This may be due to the procedural timing. The Workshop Manual Section 413-01 has been updated to reflect the corrected timing required for this procedure.

### Vehicles:

2017-2020 Continental (D544) (PL)