

## **SSM 49756: 2018-2021 Various Vehicles - FDRS Not Showing A Module Listed That Requires Updating**

Some 2018-2021 vehicles supported by FDRS may not list a software update for a module under the SW Updates tab although an SSM or TSB is published for a software update. This may be due to the module already being at the latest software level. A later software level may have been programmed at the assembly plant, during a previous dealer visit or by an over the air (OTA) update for vehicles that have automatic updates enabled in the SYNC system settings. To review a vehicle's OTA update history, visit the Connected Vehicle > OTA Dashboard tab in OASIS. Information about the OTA Dashboard can be found on FMCDealer.com when performing a search on OTA History Job Aid.

Vehicles:

2020-2021	Aviator (U611N) (TV)
2021	Bronco Sport (CX430) (HD)
2020-2021	Corsair (CX483) (TF)
2018-2021	Edge (CD539N) (DQ)
2020-2021	Escape (CX482) (TC)
2018-2021	Expedition (U553) (B8)
2020-2021	Explorer (U625N) (TW)
2021	F-150 (P702) (FD)
2018-2021	F-Super Duty (P558) NA (FE)
2018-2021	MKX/Nautilus (U540N) (D9)
2018-2021	Mustang (S550) (ZG)
2021	Mustang Mach-E (CX727N) (GW)
2018-2021	Navigator (U554) (B9)
2019-2021	Ranger P375N USA (FG)
2018-2021	Transit V363 NA (TH)