SSM 49862 -

2021 F-150 - Return Passenger Seat To Upright Position Warning Message In The IPC - Built On Or Before 18-May-2021

Some 2021 F-150 vehicles built on or before 18-May-2021 may experience a Return Passenger Seat To Upright Position warning in the message center of the instrument panel cluster (IPC) when the passenger seat is already in the upright position. This may be due to a software parameter in the driver front seat module (DSM). To correct the condition, download and run the DSM - Driver Front Seat Module (DSM) Configuration app on the latest level of the Ford diagnostic scan tool. For claiming, use causal part number 14C708 and applicable labor times from Section 10 of the Service Labor Times Standard (SLTS) Manual.

APPLICABLE VEHICLES 2021 TRUCK: FD P702N F150