

SSM 49996 - 2021 Bronco Sport - 1.5L - No Crank/No Start And/Or Illuminated MIL With Various DTCs

Some 2021 Bronco Sport vehicles equipped with a 1.5L EcoBoost engine may exhibit a no crank/no start condition with an illuminated malfunction indicator lamp (MIL) and one or more of the following diagnostic trouble codes (DTC): P093B, P2282, P0420, P062B, P21D1, P21D0, P21CF, P0710, and/or P0712. This may be due to a damaged wiring harness at the transmission cover. If damage is found, repair as necessary. Refer to Wiring Diagram Cell 005.

APPLICABLE VEHICLES
2021 CAR: HD CX430N C-SUV