

SSM 50150 - 2020-2021 Escape - Cracked Or Broken Spot Welds In The Left Front Door At The Check Arm Attachment Points In The Door Assembly

Some 2020-2021 Escape vehicles may exhibit cracks or broken spot welds in the left front door at the check arm attachment point in the door assembly. Ford has been provided feedback from fleet customers of this condition on some vehicles with high usage profiles. The door assembly and door check arm replacement is the appropriate repair for this condition. Refer to the parts catalog and Workshop Manual (WSM), Section 501-03 as required to complete the repair. For claiming, use casual part 7823552 and the applicable labor operations of Section 12 and 13 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2020 - 2021 CAR: TC CX482N ESCAPE