

**SSM 50161 - 2021 Escape Hybrid - Front-End Grille/Bumper Cover
Flutter/Rattle At 65 MPH (105 Km/h) Or Higher - Built On 10-Aug-2021 And
Through 20-Sep-21**

Some 2021 Escape Hybrid vehicles built on 10-Aug-2021 through 20-Sep-21 may exhibit a front-end flutter/rattle noise at 65 mph (105 km/h) or higher. Engineering is aware of this concern and a repair procedure should be available late October. Using the Ford Diagnosis and Repair System (FDRS), command the active grill shutters open and closed to see if the flutter/rattle noise changes. If the flutter/rattle noise does not change, continue with normal Workshop Manual, Section 100-04 for diagnostic and repair information. If the flutter/rattle noise does change, advise the customer that the vehicle is safe to drive in the meantime. Schedule a follow-up appointment for late October and when the repair procedure becomes available, contact the customer to arrange repairs. Monitor OASIS for updates.

APPLICABLE VEHICLES
2021 CAR: TC CX482N ESCAPE