

## **SSM 50336 - 2020-2021 Escape/Corsair, 2021 Bronco Sport - Communication Fault With Emissions Inspection Equipment**

Some 2020-2021 Escape/Corsair and 2021 Bronco Sport vehicles may exhibit a communication fault with emissions inspection equipment. This may be due to the software in the gateway module. To correct this condition, reprogram the gateway module to latest software level using the appropriate Ford diagnostic scan tool. Use causal part 14F642 and applicable labor times from Section 10 of the Service Labor Time Standards (SLTS) Manual.

### APPLICABLE VEHICLES

2020 - 2021 CAR: TC CX482N ESCAPE

2021 CAR: HD CX430N C-SUV

2020 - 2021 CAR: TF CX483N CORSAIR